
Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-198	Smoke	7/27/2009	ADS/TM	S15A__028MH	Dry	Yes	525.01

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S15A__028G1	S15A__028MH	S15A__008MH	181.241	8
S15A__001G1	S15A__001MH	S15A__028MH	217.518	8
S15AA_017G1	S15AA_017MH	S15A__001MH	126.252	8

Observations & Photos

Obs_ID S1028-198-OB01

Address 734 Whitmore Ave


Status Private

Source Service Lateral

Location Driveway

Nearest MH S15A__008MH

Comments Smoke from service lateral under driveway.
734 Whitmore Ave.



Picture \S1028-198-OB01-P01.jpg

Comments Side of house, 734 Whitmore Ave.

Obs_ID S1028-198-OB02

Address 734 Whitmore Ave

Status Private

Source Service Lateral

Location Driveway

Nearest MH S15A__008MH

Comments Smoke from service lateral under driveway.
734 Whitmore Ave.



Picture \S1028-198-OB02-P01.jpg

Comments Front of house, 734 Whitmore Ave.